



Cisco Unified SIP Phone 3905 Release Notes for Firmware Release 9.4(1)SR3

First Published: 2018-12-12

Last Modified: 2021-07-05

Cisco Unified SIP Phone 3905 Release Notes for Firmware Release 9.4(1)SR3

These release notes support the Cisco Unified SIP Phone 3905 running Firmware Release 9.4(1)SR3.

The following table lists the Cisco Unified Communications Manager release and protocol compatibility for the Cisco Unified SIP Phone 3905.

Cisco Unified IP Phone	Protocol	Cisco Unified Communications Manager
Cisco Unified SIP Phone 3905	SIP	Cisco Unified Communications Manager Release 7.1(5) and later.

Related Documentation

Use the following sections to obtain related information.

Cisco Unified SIP Phone 3905 Documentation

Refer to publications that are specific to your language, phone model and Cisco Unified Communications Manager release. Navigate from the following documentation URL:

<https://www.cisco.com/c/en/us/support/collaboration-endpoints/unified-sip-phone-3900-series/tsd-products-support-series-home.html>

Cisco Unified Communications Manager Documentation

See the *Cisco Unified Communications Manager Documentation Guide* and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following documentation URL:

<https://www.cisco.com/c/en/us/support/unified-communications/unified-communications-manager-callmanager/tsd-products-support-series-home.html>

New and Changed Features

This release contains no new or changed features.

Installation

Install the Firmware Release on the Cisco Unified Communications Manager

Before using the Cisco Unified SIP Phone 3905 Firmware Release 9.4(1)SR3 with Cisco Unified Communications Manager, you must install the latest firmware on all Cisco Unified Communications Manager servers in the cluster.

Procedure

- Step 1** Go to the following URL:
<http://software.cisco.com/download/navigator.html?mdfid=280896546&i=rm>
- Step 2** Choose **Cisco Unified SIP Phone 3900 Series**.
- Step 3** Choose **Cisco Unified SIP Phone 3905**.
- Step 4** Choose **Session Initiation Protocol (SIP) Software**.
- Step 5** In the Latest Releases folder, choose **9.4(1)SR3**.
- Step 6** Select the following firmware file, click the **Download** or **Add to cart** button, and follow the prompts:
- cmterm-3905.9-4-1SR3.cop.sgn
- Note** If you added the firmware file to the cart, click the **Download Cart** link when you are ready to download the file.
- Step 7** Click the + next to the firmware file name in the Download Cart section to access additional information about this file. The hyperlink for the readme file is in the Additional Information section, which contains installation instructions for the corresponding firmware:
- cmterm-3905-sip-9-4-1SR3-readme.html
- Step 8** Follow the instructions in the readme file to install the firmware.
-

Install the Firmware Zip Files

If a Cisco Unified Communications Manager is not available to load the installer program, the following .zip files are available to load the firmware.

- cmterm-3905.9-4-1SR3.zip

Firmware upgrades over the WLAN interface may take longer than upgrades using a wired connection. Upgrade times over the WLAN interface may take more than an hour, depending on the quality and bandwidth of the wireless connection.

Procedure

- Step 1** Go to the following URL:
<http://software.cisco.com/download/navigator.html?mdfid=284883944&i=rm>

- Step 2** Choose **Cisco Unified SIP Phone 3900 Series**.
- Step 3** Choose **Cisco Unified SIP Phone 3905**.
- Step 4** Choose **Session Initiation Protocol (SIP) Software**.
- Step 5** In the Latest Releases folder, choose **9.4(1)SR3**.
- Step 6** Download the relevant zip files.
- Step 7** Unzip the files.
- Step 8** Manually copy the unzipped files to the directory on the TFTP server. See *Cisco Unified Communications Operating System Administration Guide* for information about how to manually copy the firmware files to the server.

Limitations and Restrictions

Voice VLAN and IPv6 Limitation

If the PC attached to the PC port of the phone is using IPv6, we recommend that the PC Voice LAN access be disabled. This ensures that the PC cannot connect to the Voice VLAN.

Phone Behavior During Times of Network Congestion

Anything that degrades network performance can affect phone audio and, in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

On-Hook Transfer Limitation in SIP Phones

When the Cisco Unified Communications Manager **Transfer On-Hook Enabled** field is enabled, users might report a problem with direct call transfer in SIP phones. If the user transfers the call and immediately goes on hook before they hear the ring signal, the call may drop instead of being transferred.

The user needs to hear the ring signal so that they can be sure that the call is being routed.

Language Limitation

There is no localized Keyboard Alphanumeric Text Entry (KATE) support for the following Asian locales:

- Chinese (China)
- Chinese (Hong Kong)
- Chinese (Taiwan)
- Japanese (Japan)
- Korean (Korea Republic)

The default English (United States) KATE is presented to the user instead.

For example, the phone screen will show text in Korean, but the **2** key on the keypad will display **a b c 2**
A B C.

Caveats

Access Cisco Bug Search

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of the following:

- All severity level 1 or 2 bugs
- Significant severity level 3 bugs

You can search for problems by using Cisco Bug Search.

Before you begin

To access Cisco Bug Search, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

Procedure

-
- Step 1** To access Cisco Bug Search, go to:
<https://tools.cisco.com/bugsearch>
- Step 2** Log in with your Cisco.com user ID and password.
- Step 3** To look for information about a specific problem, enter the bug ID number in the Search for field, then press **Enter**.
-

Open Caveats

The following table lists severity 1, 2, and 3 defects that are open for the Cisco Unified SIP Phone 3905 for Firmware Release 9.4(1)SR3.

For more information about an individual defect, you can access the online record for the defect using the Bug Toolkit. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, the table reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in [Access Cisco Bug Search, on page 4](#).

Table 1: Open Caveats for Firmware Release 9.4(1)SR3

Identifier	Headline
CSCug96869	Not request new address after DHCPv6 assigned address duplicated
CSCuh02720	Take long time to bootup if DHCPv4 server shutdown

Identifier	Headline
CSCuh10981	No DSCP to 802.1Q priority mapping for both IPv4 and IPv6
CSCuh15911	Phone should keep re-provision if version stamp mismatch
CSCuh91119	Phone stuck during Codenomicon HTTP Server/TCP for IPv4 suite testing
CSCuj73157	Not re-request config file if get TFTP "Disk full or allocation exceed"
CSCun58512	Can't transfer after set CFwdAll and answer call in same pickup group

Resolved Caveats

The following table lists severity 1, 2, and 3 defects that are resolved for the Cisco Unified SIP Phone 3905 for Firmware Release 9.4(1)SR3.

For more information about an individual defect, you can access the online record for the defect using the Bug Toolkit. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, the table reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in [Access Cisco Bug Search, on page 4](#).

Table 2: Resolved Caveats for Firmware Release 9.4(1)SR3

Identifier	Headline
CSCus15722	3905 Second Port Status TLV
CSCux45004	One way audio between CP-3905 and Analog phone
CSCvb50752	Authentication timing issue causes InformaCast paging failure
CSCve90919	Wrong value on display of calling party number if the remote DN contain '#'
CSCve81092	FAC window doesn't disappear from phone screen if 180 ringing/183 SP message is missing
CSCvc88174	3905 unable to receive pages from InformaCast due to error in html URL encoding
CSCvd42786	3905 one-way issue because of microphone is in power down state during the problematic call
CSCve36604	3905 stop sending RTP packets because of timing issue during the audio channel open/close procedure
CSCvf51115	3905 Phones displaying wrong Network Mask (Prefix) of /128 with Stateful DHCPv6
CSCvg23733	CP3905 ignore the SIP registration Port configuration when failover to secondary CUCM
CSCur65489	Low ringer Volume on 3905 Phones
CSCvi33607	Busy tone not played after 3905 phone receives 600 response for INVITE

Identifier	Headline
CSCvi78353	3905 Phone freezes when previous call is disconnected
CSCvk49825	3905 phones do not register back to the primary node after failing over to the secondary
CSCvm54764	3905 phone gets stuck when it attempts a transfer and the transferred to number declines the call.
CSCvk74063	3905 Paging audio is sometimes garbled.
CSCvk30428	3905 Call Pickup inconsistent behavior

Cisco Unified Communication Manager Public Keys

To improve software integrity protection, new public keys are used to sign cop files for Cisco Unified Communications Manager Release 10.0.1 and later. These cop files have “k3” in their name. To install a k3 cop file on a pre-10.0.1 Cisco Unified Communications Manager, consult the README for the `cisco.com.version3-keys.cop.sgn` to determine if this additional cop file must first be installed on your specific Cisco Unified Communications Manager version. If these keys are not present and are required, you will see the error “The selected file is not valid” when you try to install the software package.

Unified Communications Manager Endpoints Locale Installer

By default, Cisco IP Phones are set up for the English (United States) locale. To use the Cisco IP Phones in other locales, you must install the locale-specific version of the Unified Communications Manager Endpoints Locale Installer on every Cisco Unified Communications Manager server in the cluster. The Locale Installer installs the latest translated text for the phone user interface and country-specific phone tones on your system so that they are available for the Cisco IP Phones.

To access the Locale Installer required for a release, access <https://software.cisco.com/download/navigator.html?mdfid=286037605&flowid=46245>, navigate to your phone model, and select the Unified Communications Manager Endpoints Locale Installer link.

For more information, see the documentation for your particular Cisco Unified Communications Manager release.



Note The latest Locale Installer may not be immediately available; continue to check the website for updates.

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

Cisco IP Phone Documentation Updates on Cisco Unified Communications Manager

The Cisco Unified Communications Manager Self Care Portal (Release 10.0 and later) and User Options web pages (Release 9.1 and earlier) provide links to the IP Phone user guides in PDF format. These user guides are stored on the Cisco Unified Communications Manager and are up to date when the Cisco Unified Communications Manager release is first made available to customers.

After a Cisco Unified Communications Manager release, subsequent updates to the user guides appear only on the Cisco website. The phone firmware release notes contain the applicable documentation URLs. In the web pages, updated documents display “Updated” beside the document link.



Note The Cisco Unified Communications Manager Device Packages and the Unified Communications Manager Endpoints Locale Installer do not update the English user guides on the Cisco Unified Communications Manager.

You and your users should check the Cisco website for updated user guides and download the PDF files. You can also make the files available to your users on your company website.



Tip You may want to bookmark the web pages for the phone models that are deployed in your company and send these URLs to your users.

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2021 Cisco Systems, Inc. All rights reserved.