



Cisco Unified IP Phone 7900 Series Release Notes for Firmware Release 9.3(1)SR2

First Published: February 14, 2013

Last Modified: March 27, 2015

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <http://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2015 Cisco Systems, Inc. All rights reserved.



CONTENTS

CHAPTER 1

Cisco Unified IP Phone 7900 Series Release Notes for Firmware Release 9.3(1)SR2 1

Introduction 1

New and Changed Features 3

 Firmware Release 9.3(1)SR2 Security Enhancements 3

Related Documentation 3

 Cisco Unified IP Phone 7900 Series Documentation 3

 Cisco Unified Communications Manager Documentation 3

 Cisco Business Edition 5000 Documentation 4

Installation 4

 Installation Requirements 4

 SCCP Firmware Upgrade Issues 4

 SIP Firmware Upgrade Issues 5

 Install Latest Cisco Unified Communications Manager Release 5

 Install Cisco Unified Communications Manager Device Packs 5

 Install Firmware Release on Cisco Unified Communications Manager 6

 Cisco Unified IP Phone Expansion Module Firmware Installation 8

 Cisco Unified IP Phone Expansion Module 7914 Installation 8

 Cisco Unified IP Phone Expansion Module 7914 Firmware Upgrade Issues 8

 Install Cisco Unified IP Phone Expansion Module 7914 Firmware 9

 Cisco Unified IP Phone Expansion Modules 7915 and 7916 Installation 10

 Cisco Unified IP Phone Expansion Modules 7915 and 7916 Firmware Issues 10

 Install Cisco Unified IP Phone Expansion Modules 7915 and 7916 Firmware 10

Limitations and Restrictions 11

 Phone Behavior During Times of Network Congestion 11

Unified Communications Manager Endpoints Locale Installer 11

Caveats 12

 Access Cisco Bug Search 12

 Open Caveats 12

Resolved Caveats **14**
Cisco IP Phone Firmware Support Policy **14**
Documentation, Service Requests, and Additional Information **15**



CHAPTER

1

Cisco Unified IP Phone 7900 Series Release Notes for Firmware Release 9.3(1)SR2

- [Introduction, page 1](#)
- [New and Changed Features, page 3](#)
- [Related Documentation, page 3](#)
- [Installation, page 4](#)
- [Limitations and Restrictions, page 11](#)
- [Unified Communications Manager Endpoints Locale Installer, page 11](#)
- [Caveats, page 12](#)
- [Cisco IP Phone Firmware Support Policy, page 14](#)
- [Documentation, Service Requests, and Additional Information, page 15](#)

Introduction

These release notes support the Cisco Unified IP Phones 7900 Series running SCCP and SIP Firmware Release 9.3(1)SR2.

Firmware Release 9.3(1)SR2 applies to the following phones:

- Cisco Unified IP Phone 7906
- Cisco Unified IP Phone 7911
- Cisco Unified IP Phone 7931
- Cisco Unified IP Phone 7941
- Cisco Unified IP Phone 7941G-GE
- Cisco Unified IP Phone 7942
- Cisco Unified IP Phone 7945
- Cisco Unified IP Phone 7961

- Cisco Unified IP Phone 7961G-GE
- Cisco Unified IP Phone 7962
- Cisco Unified IP Phone 7965
- Cisco Unified IP Phone 7970
- Cisco Unified IP Phone 7971
- Cisco Unified IP Phone 7975

The following table lists the Cisco Unified Communications Manager release and protocol compatibility for the Cisco Unified IP Phones.

Table 1: Cisco Unified IP Phones, Cisco Unified Communications Manager, and Firmware Release Compatibility

Cisco Unified IP Phone	Protocol	Cisco Unified Communications Manager
Cisco Unified IP Phones 7906G, 7911G, 7941G, 7941G-GE, 7961G, 7961G-GE, 7970G, and 7971G-GE	SCCP	Cisco Unified Communications Manager Release 6.0 and later Cisco Unified CallManager Release 5.1, 5.0, 4.3, 4.2, 4.1, 4.0 Cisco CallManager Release 3.3
Cisco Unified IP Phones 7906G, 7911G, 7941G, 7941G-GE, 7961G, 7961G-GE, 7970G, and 7971G-GE	SIP	Cisco Unified Communications Manager Release 6.0 and later Cisco Unified CallManager Release 5.1 and 5.0
Cisco Unified IP Phone 7931G	SCCP	Cisco Unified Communications Manager Release 6.0, 6.1, 7.0 and later
Cisco Unified IP Phone 7931G	SIP	Cisco Unified Communications Manager Release 7.0 and later
Cisco Unified IP Phones 7942G, 7945G, 7962G, 7965G, and 7975G	SCCP	Cisco Unified Communications Manager Release 6.x and later Cisco Unified CallManager Release 5.1, 4.3(2)
Cisco Unified IP Phones 7942G, 7945G, 7962G, 7965G, and 7975G	SIP	Cisco Unified Communications Manager Release 6.x and later Cisco Unified CallManager Release 5.1

**Note**

Firmware Release 9.3(1)SR2 is designed and tested to interoperate with Cisco call control, most notably Cisco Unified Communications Manager Release 9.0(1). Although SIP firmware is IETF RFC 3261 compliant, it is not supported by Cisco TAC or Engineering for use with non-Cisco call control systems.

New and Changed Features

The following sections describe the new and changed features in this release.

Firmware Release 9.3(1)SR2 Security Enhancements

Firmware Release 9.3(1)SR2 contains the following security enhancements:

- The phone does not request authorized key information from the TFTP server. Without the authorized keys, the administrator must enter the SSH user id and password to connect to the phone for debugging.
- The debugging *setmask* commands are added to the phone debug shell. Making the commands available in the debug shell removes the need for the default user account.
- The ability to log into a default user account has been removed. Phone debugging can only be performed using the debug account.
- The ability to log into the phone from the AUX port on the phone has been removed.

This feature had no user impact.

Related Documentation

Use the following sections to obtain related information.

Cisco Unified IP Phone 7900 Series Documentation

See the publications that are specific to your language, phone model, and Cisco Unified Communications Manager release. Navigate from the following documentation URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/unified-ip-phone-7900-series/tsd-products-support-general-information.html>

Cisco Unified Communications Manager Documentation

See the *Cisco Unified Communications Manager Documentation Guide* and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following documentation URL:

<http://www.cisco.com/c/en/us/support/unified-communications/unified-communications-manager-callmanager/tsd-products-support-series-home.html>

Cisco Business Edition 5000 Documentation

See the *Cisco Business Edition 5000 Documentation Guide* and other publications that are specific to your Cisco Business Edition 5000 release. Navigate from the following URL:

<http://www.cisco.com/c/en/us/support/unified-communications/business-edition-5000/tsd-products-support-series-home.html>

Installation

Installation Requirements

Before you install the firmware release, you must ensure that your Cisco Unified Communications Manager is running the latest device pack.



Important

If your Cisco Unified Communications Manager does not have the required device pack to support this firmware release, the firmware may not work correctly.

For information on the Cisco Unified Communications Manager Device Packs, see http://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cucm/compat/devpack_comp_mtx.html.

SCCP Firmware Upgrade Issues

This section applies to the Cisco Unified IP Phones 7975G, 7971G-GE, 7970G, 7965G, 7962G, 7961G-GE, 7961G, 7945G, 7942G, 7941G-GE, 7941G, 7931G, 7911G, and 7906G.



Note

For all SCCP firmware upgrades from firmware release versions earlier than 8.3(3) to Version 9.3(1) or later, you must first upgrade your phone firmware to an intermediate version (8.3(3) to 8.5(2)) and then upgrade to 9.3(1).

The following upgrade issues apply:

- If you are currently running firmware earlier than 6.0(2) on a Cisco Unified IP Phone and want to upgrade to 8.x(x), you must first install an intervening 7.0(x) load to prevent upgrade failure. Cisco recommends using the most recent 7.0(3) load as the intervening load to avoid lengthy upgrade times.
- If you are currently running firmware 6.0(2) to 7.0(2) on a Cisco Unified IP Phone and want to upgrade to 8.x(x), you can do so directly. However, expect the upgrade to take twice as long as usual.

SIP Firmware Upgrade Issues

For all SIP firmware upgrades from firmware release versions earlier than 8.3(3) to Version 9.3(1) or later, you must first upgrade your phone firmware to an intermediate version (8.3(3) to 8.5(2)) and then upgrade to 9.3(1).

The following upgrade issues apply:

- If you are currently running firmware 6.0(2) to 7.0(2) on a Cisco Unified IP Phone and want to upgrade to 8.x(x), be aware that upgrading will take up to twice as long to complete as usual.
- Device packs are required to enable IP Phones in the Cisco Unified Communications Manager database. For Cisco Unified CallManager 4.2 and earlier, these device packs are required. For Cisco Unified CallManager 4.3 and Cisco Unified Communications Manager 6.0 and later, you must run the device pack and reboot the Cisco Unified Communications Manager server.

Install Latest Cisco Unified Communications Manager Release

Before using the Cisco Unified IP Phone with Cisco Unified Communications Manager, your Cisco Unified Communications Manager servers must be running a version of the server software that supports the phones. All Cisco Unified Communications Manager servers in the cluster must support the phones. For information about the minimum Cisco Unified Communications Manager software version that the phone requires, see the introductory sections of these release notes.

For more information on Cisco Unified Communications Manager installations and upgrades, see the documents for your Cisco Unified Communications Manager version at the following location: http://www.cisco.com/en/US/products/sw/voicesw/ps556/prod_installation_guides_list.html

To download and install the Cisco Unified Communications Manager version, perform these steps.

Procedure

-
- Step 1** Go to the following URL:
<http://www.cisco.com/cisco/software/navigator.html?mdfid=268439621&catid=278875240>
 - Step 2** Choose your Cisco Unified Communications Manager version.
 - Step 3** Choose the appropriate software type.
 - Step 4** Hover over the desired file. When the popup window displays, click the **Readme** link to open the readme file.
 - Step 5** Choose **Download** or **Add to cart** for the desired file.
 - Step 6** Use the instructions in the readme file to install the updated file on the Cisco Unified Communications Manager.
-

Install Cisco Unified Communications Manager Device Packs

Device packs are required to enable IP phones in the Cisco Unified Communications Manager database. For information about compatible device packs, see http://www.cisco.com/en/US/docs/voice_ip_comm/cucm/compat/devpack_comp_mtx.html.

For Cisco Unified CallManager 4.2 and earlier, these device packs are required. For Cisco Unified CallManager 4.3 and Cisco Unified Communications Manager 6.0 and later, you must run the device pack and reboot the Cisco Unified Communications Manager server.

To install the device packs, follow these steps.

Procedure

- Step 1** Go to the following URL:
<http://www.cisco.com/cisco/software/navigator.html?mdfid=268439621&flowid=21301>
 - Step 2** Choose your Cisco Unified Communications Manager version.
 - Step 3** Hover over the desired device pack. When the popup window displays, click the **Readme** link to open the readme file.
 - Step 4** Choose **Download** or **Add to cart** for the desired device pack.
 - Step 5** Use the instructions in the readme file to install the updated device pack on the Cisco Unified Communications Manager.
-

Install Firmware Release on Cisco Unified Communications Manager

Before using the Cisco Unified IP Phone 7900 Series Firmware Release 9.3(1)SR2 with Cisco Unified Communications Manager, you must install the latest firmware on all Cisco Unified Communications Manager servers in the cluster.

Procedure

- Step 1** Go to the following URL:
<http://www.cisco.com/cisco/software/navigator.html?mdfid=268437892&flowid=5293>
- Step 2** Choose **Cisco Unified IP Phones 7900 Series**.
- Step 3** Choose your phone type.
- Step 4** Choose one of the following firmware types:
 - **Skiny Client Control Protocol (SCCP) Software**
 - **Session Initiation Protocol (SIP) Software**
- Step 5** In the Latest Releases folder, choose **9.3(1)SR2**.
- Step 6** Select one of the following firmware files, click **Download Now** or **Add to cart** button, and follow the prompts:
 - For Cisco Unified CallManager 4.2 and earlier (firmware files only):
 - `cmterm-7975-sccp.9-3-1SR2-1.zip`
 - `cmterm-7970_7971-sccp.9-3-1SR2-1.zip`
 - `cmterm-7945_7965-sccp.9-3-1SR2-1.zip`

- cmterm-7942_7962-sccp.9-3-1SR2-1.zip
 - cmterm-7941_7961-sccp.9-3-1SR2-1.zip
 - cmterm-7911_7906-sccp.9-3-1SR2-1.zip
- For Cisco Unified CallManager 4.3:
 - cmterm-7975-sccp.9-3-1SR2-1.exe
 - cmterm-7970_7971-sccp.9-3-1SR2-1.exe
 - cmterm-7945_7965-sccp.9-3-1SR2-1.exe
 - cmterm-7942_7962-sccp.9-3-1SR2-1.exe
 - cmterm-7941_7961-sccp.9-3-1SR2-1.exe
 - cmterm-7911_7906-sccp.9-3-1SR2-1.exe
- For Cisco Unified CallManager 5.0(4) and later:
 - cmterm-7975-sccp.9-3-1SR2-1.cop.sgn
 - cmterm-7970_7971-sccp.9-3-1SR2-1.cop.sgn
 - cmterm-7945_7965-sccp.9-3-1SR2-1.cop.sgn
 - cmterm-7942_7962-sccp.9-3-1SR2-1.cop.sgn
 - cmterm-7941_7961-sccp.9-3-1SR2-1.cop.sgn
 - cmterm-7911_7906-sccp.9-3-1SR2-1.cop.sgn
- For Cisco Unified Communications Manager 6.0 and later:
 - cmterm-7931-sccp.9-3-1SR2-1.cop.sgn
- For Cisco Unified CallManager 5.0 and later (firmware files only):
 - cmterm-7975-sip.9-3-1SR2-1.zip
 - cmterm-7970_7971-sip.9-3-1SR2-1.zip
 - cmterm-7945_7965-sip.9-3-1SR2-1.zip
 - cmterm-7942_7962-sip.9-3-1SR2-1.zip
 - cmterm-7941_7961-sip.9-3-1SR2-1.zip
 - cmterm-7911_7906-sip.9-3-1SR2-1.zip
- For Cisco Unified CallManager 5.0(4) and later:
 - cmterm-7975-sip.9-3-1SR2-1.cop.sgn
 - cmterm-7970_7971-sip.9-3-1SR2-1.cop.sgn
 - cmterm-7945_7965-sip.9-3-1SR2-1.cop.sgn
 - cmterm-7942_7962-sip.9-3-1SR2-1.cop.sgn

- cmterm-7941_7961-sip.9-3-1SR2-1.cop.sgn
- cmterm-7911_7906-sip.9-3-1SR2-1.cop.sgn

Note If you added the firmware file to the cart, click the **Download Cart** link when you are ready to download the file.

Step 7 Click the + next to the firmware file name in the Download Cart section to access additional information about this file. The hyperlink for the readme file is in the Additional Information section, which contains installation instructions for the corresponding firmware:

- cmterm-7911_7906-sccp.9-3-1SR2-1-readme.html
- cmterm-7911_7906-sip.9-3-1SR2-1-readme.html
- cmterm-7931-sccp.9-3-1SR2-1-readme.html
- cmterm-7931-sip.9-3-1SR2-1-readme.html
- cmterm-7941_7961-sccp.9-3-1SR2-1-readme.html
- cmterm-7941_7961-sip.9-3-1SR2-1-readme.html
- cmterm-7942_7962-sccp.9-3-1SR2-1-readme.html
- cmterm-7942_7962-sip.9-3-1SR2-1-readme.html
- cmterm-7945_7965-sccp.9-3-1SR2-1-readme.html
- cmterm-7945_7965-sip.9-3-1SR2-1-readme.html
- cmterm-7970_7971-sccp.9-3-1SR2-1-readme.html
- cmterm-7970_7971-sip.9-3-1SR2-1-readme.html
- cmterm-7975-sccp.9-3-1SR2-1-readme.html
- cmterm-7975-sip.9-3-1SR2-1-readme.html

Step 8 Follow the instructions in the readme file to install the firmware.

Cisco Unified IP Phone Expansion Module Firmware Installation

The following sections describe the Cisco Unified IP Phone Expansion Module firmware installation.

Cisco Unified IP Phone Expansion Module 7914 Installation

This section describes how to install Cisco Unified IP Phone Expansion Module 7914.

Cisco Unified IP Phone Expansion Module 7914 Firmware Upgrade Issues

The Cisco Unified IP Phones 7906G, 7911G, 7941G, 7941G-GE, 7942G, and 7945G, do not support the Cisco Unified IP Phone Expansion Module 7914.

You can add a maximum of two Expansion Modules to the Cisco Unified IP Phones 7961G, 7961G-GE, 7965G, 7970G, 7971G, and 7975G.

The filename for Cisco Unified IP Phone Expansion Module 7914 indicates that it is for use with SCCP; however, it supports both SCCP and SIP. This applies to IP Phones using Cisco Unified Communications Manager 7.0.

If you are using the Cisco Unified IP Phone Expansion Module 7914, you must upgrade the expansion module to firmware release S00105000400 before using the phone to support relevant features on your expansion module.

Install Cisco Unified IP Phone Expansion Module 7914 Firmware

To download and install the firmware, perform these steps:

Procedure

- Step 1** Go to the following URL:
<http://www.cisco.com/cisco/software/navigator.html?mdfid=269065653&i=rm>
- Step 2** Log in to the **Tools and Resources Download** page.
- Step 3** Choose the IP Telephony folder by clicking +.
- Step 4** Choose **IP Phones > Cisco Unified IP Phones 7900 Series**.
- Step 5** Choose **Cisco Unified IP Phone Expansion Module 7914**.
- Step 6** Choose **Skiny Client Control Protocol (SCCP) Software**.
- Step 7** Choose **5.0(4)** under the Latest Releases folder.
- Step 8** To download the firmware for Cisco Unified IP Phone Expansion Module 7914, click the **Download Now** or **Add to cart** button and follow the prompts:
- For Cisco Unified Communications Manager 4.3 and earlier:
cmterm-7914-sccp.5-0-4.exe
 - For Cisco Unified Communications Manager 5.0(1), 5.0(2), and 5.0(3):
cmterm-7914-sccp.5-0-4.cop
 - For Cisco Unified Communications Manager 5.0(4) and later:
cmterm-7914-sccp.5-0-4.cop.sgn
- Step 9** If you added the firmware file to the cart, click the **Download Cart** link when you are ready to download the file.
- Step 10** Click the + next to the firmware file name in the Download Cart section to access additional information about this file. The hyperlink for the readme file is in the Additional Information section, which contains installation instructions for the corresponding firmware:
cmterm-7914-sccp.5-0-4.readme.html
-

Cisco Unified IP Phone Expansion Modules 7915 and 7916 Installation

This section describes how to install Cisco Unified IP Phone Expansion Modules 7915 and 7916.

Cisco Unified IP Phone Expansion Modules 7915 and 7916 Firmware Issues

Before you use the Cisco Unified IP Phone Expansion Module 7916, you must load the expansion module with firmware release B016-1-0-4-2 before using the phone to support relevant features on your expansion module.

Before you use the Cisco Unified IP Phone Expansion Module 7915, you must load the expansion module with firmware release B015-1-0-4-2 before using the phone to support relevant features on your expansion module.

The Cisco Unified IP Phones 7962G, 7965G, and 7975G support the Cisco Unified IP Phone Expansion Modules 7915 and 7916. You can add a maximum of two expansion modules to these phones.

Install Cisco Unified IP Phone Expansion Modules 7915 and 7916 Firmware

To download and install the firmware, perform these steps:

Procedure

-
- Step 1** Choose **Cisco Unified IP Expansion Module 7916** or **Cisco Unified IP Expansion Module 7915**.
 - Step 2** Choose the IP Telephony folder by clicking +.
 - Step 3** Choose **IP Phones > Cisco Unified IP Phones 7900 Series**.
 - Step 4** Choose **Cisco Unified IP Expansion Module 7916** or **Cisco Unified IP Expansion Module 7915**.
 - Step 5** Choose **1.0(4)** under the Latest Releases folder.
 - Step 6** To download the SIP firmware for the Cisco Unified IP Phone, click the **Download Now** or **Add to cart** button and follow the prompts:
For Cisco Unified CallManager 4.3 and 4.2 (SCCP firmware files only):

- cmterm-7915.1-0-4.zip
- cmterm-7916.1-0-4.zip

For Cisco Unified Communications Manager 5.1 and later:

- cmterm-7915.1-0-4.cop.sgn
- cmterm-7916.1-0-4.cop.sgn

For Cisco Unified CallManager 4.3 and 4.2 (SCCP only):

- cmterm-7915.1-0-4.exe
- cmterm-7916.1-0-4.exe

- Step 7** If you added the firmware file to the cart, click the **Download Cart** link when you are ready to download the file.
- Step 8** Click the + next to the firmware file name in the Download Cart section to access additional information about this file. The hyperlink for the readme file is in the Additional Information section, which contains installation instructions for the corresponding firmware:
cmterm-7915_7916.1-0-4-readme.html
-

Limitations and Restrictions

Phone Behavior During Times of Network Congestion

Anything that degrades network performance can affect Cisco IP Phone voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

To reduce or eliminate any adverse effects to the phones, schedule administrative network tasks during a time when the phones are not being used or exclude the phones from testing.

Unified Communications Manager Endpoints Locale Installer

By default, Cisco IP Phones are set up for the English (United States) locale. To use the Cisco IP phones in other locales, you must install the locale-specific version of the Unified Communications Manager Endpoints Locale Installer on every Cisco Unified Communications Manager server in the cluster. The Locale Installer installs the latest translated text for the phone user interface and country-specific phone tones on your system so that they are available for the Cisco IP Phones.

To access the Locale Installer required for a release, access <http://software.cisco.com/download/navigator.html?mdfid=286037605&flowid=46245>, navigate to your phone model, and select the Unified Communications Manager Endpoints Locale Installer link.

For more information, see the “Locale Installer” section in the *Cisco Unified Communications Operating System Administration Guide*.

**Note**

The latest Locale Installer may not be immediately available; continue to check the website for updates.

Caveats

This section describes the resolved and open caveats, and provides information on accessing the Cisco Software Bug Toolkit.

Access Cisco Bug Search

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of the following:

- All severity level 1 or 2 bugs
- Significant severity level 3 bugs

You can search for problems by using the Cisco Bug Search.

Before You Begin

To access Cisco Bug Search, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

Procedure

-
- Step 1** To access the Cisco Bug Search, go to:
<https://tools.cisco.com/bugsearch>
- Step 2** Log in with your Cisco.com user ID and password.
- Step 3** To look for information about a specific problem, enter the bug ID number in the Search for field, then press **Enter**.
-

Open Caveats

The following table lists severity 1, 2, and 3 defects that are open for the Cisco Unified IP Phones that use Firmware Release 9.3(1)SR2.

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL that is shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, the table reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in [Access Cisco Bug Search, on page 12](#).

Table 2: Open Caveats for Firmware Release 9.3(1)SR2

Identifier	Headline
CSCsy82318	MIDP Mutable image is not displayed on a 7941
CSCtj61369	phone stuck during PFS upgrading/downgrading
CSCtk56477	FR23:When pull out the net,use a https connection, wait no time out.
CSCtl83604	IDH: Cisco IP phone 7941 does not send out CDP during bootup
CSCtn25563	LSC install/upgrade failed or cancelled when CCM Failover/Fallback
CSCtr31587	TFTP error on the phone status, when testing with 200k endpoints.
CSCtr70351	Device occasionally hard reset due to segmentation error
CSCtr99139	Blowing to the headset microphone brings some noise.
CSCtu36302	Customized ring tones are not ringing for 79XX series Phones.
CSCty85123	wrong behavior of "<<" in edit dial state.
CSCtz26688	Call does not disconnect after getting reorder - SIP Phone
CSCtz26712	Audio issue with ilbc codec - 7911 phone
CSCtz33592	Phones are blocked in "Configuring ip" after longtime upgrade/downgrade.
CSCtz37296	sip phone : 'CFwdAll' button work as create call in PLAR feature
CSCua06647	ETSGJ-CH: 7961 IP Phone restarted unexpectedly while debugging thru SSH
CSCua11280	PD always display login UI when you logout successfully
CSCua16007	7911 phone limitation for octo-line
CSCud47731	7941/61/70/71 clipping audio with speakerphone with FW 8.5.4, 9.2.1
CSCud66570	7931 Peer Firmware Sharing always disabled
CSCue31340	Phone directory does not work with default HTTPS port
CSCue54945	Arabic UAE locale language: Corporate directory search reloads phones
CSCud74471	7975 Few Arabic letters are not showing properly
CSCue13562	7965 one way audio using Any connect IOS VPN
CSCue30927	Group picture display is missing on 7900 phones

Resolved Caveats

The following table lists severity 1, 2, and 3 defects that are resolved for the Cisco Unified IP Phones that use Firmware Release 9.3(1)SR2.

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL that is shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, the table reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in [Access Cisco Bug Search](#), on page 12.

Table 3: Resolved Caveats for Firmware Release 9.3(1)SR2

Identifier	Headline
CSCub94152	Phone behavior is wrong if try to transfer to a non-exist number
CSCuc71497	Phone does not release the call when going on-hook
CSCuc73107	7942/62 fail from full duplex to half at ethernet outage
CSCuc76335	Phone will restart after visiting phone web page using https
CSCuc95742	7942 SIP42.9-2-3S has softkey problem when the phone goes to SRTS mode.
CSCud60349	EAP-TLS authentication fails when ISE is using chained certificate
CSCue04937	Disable default user account and console login on TNP phones
CSCue04970	SSH auth-key file will not be sent to phone
CSCue04972	Settmak command from default user shell is ported into debug shell
CSCue05058	Phone should support ignore-early-media=true in Call-Info Header
CSCue33263	79XX phones showing the incorrect time for certain time zones 9.3.1ES11

Cisco IP Phone Firmware Support Policy

For information on the support policy for Cisco IP Phones, see <http://www.cisco.com/c/en/us/support/docs/collaboration-endpoints/unified-ip-phone-7900-series/116684-technote-ipphone-00.html>.

Documentation, Service Requests, and Additional Information

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.



INDEX

B

bug [12](#)

D

device pack [5](#)
installation [5](#)

