



# Cisco Unified IP Phone 7960G and 7940G (SIP) Release Notes for Firmware Release 8.8

---

September 20, 2007

Use these release notes with the Cisco Unified IP Phone 7960G and 7940G running SIP firmware release 8.8.

## Contents

These release notes provide the following information:

- [Related Documentation, page 1](#)
- [Installation Notes, page 1](#)
- [Caveats, page 2](#)
- [Obtaining Documentation, Obtaining Support, and Security Guidelines, page 3](#)

## Related Documentation

### Cisco SIP IP Phone Documentation

Refer to publications that are specific to your language, phone model and Cisco Unified Communications Manager release. Navigate from the following documentation URL:

[http://www.cisco.com/en/US/products/sw/voicesw/ps2156/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/sw/voicesw/ps2156/tsd_products_support_series_home.html)

## Installation Notes

Before using the Cisco Unified IP Phone 7960G or 7940G (SIP), you must install the latest firmware.

The firmware image names are:

- POS3-08-8-00.loads



---

**Americas Headquarters:**  
**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2007 Cisco Systems, Inc. All rights reserved.

- P003-08-8-00.sbn
- POS3-08-8-00.sb2
- P003-08-8-00.bin

To install the firmware, go to the following URL:

<http://www.cisco.com/cgi-bin/tablebuild.pl/sip-ip-phone7960>

## Caveats

This section includes these topics:

- [Using Bug Toolkit, page 2](#)
- [Open Caveats, page 2](#)
- [Resolved Caveats, page 3](#)

## Using Bug Toolkit

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of:

- All severity level 1 or 2 bugs.
- Significant severity level 3 bugs.

You can search for problems by using the Cisco Software Bug Toolkit.

To access Bug Toolkit, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

To use the Software Bug Toolkit, follow these steps:

### Procedure

- 
- |               |  |
|---------------|--|
| <b>Step 1</b> | To access the Bug Toolkit, go to <a href="http://tools.cisco.com/Support/BugToolKit/action.do?hdnAction=searchBugs">http://tools.cisco.com/Support/BugToolKit/action.do?hdnAction=searchBugs</a> . |
| <b>Step 2</b> | Log on with your Cisco.com user ID and password.   |
| <b>Step 3</b> | To look for information about a specific problem, enter the bug ID number in the “Search for bug ID” field, then click <b>Go</b> .   |
- 

## Open Caveats

[Table 1](#) lists Severity 1, 2, and 3 defects that are open for the Cisco Unified IP Phone 7960G and 7940G (SIP) using firmware release 8.8.

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that [Table 1](#) reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in the “[Using Bug Toolkit](#)” section on page 2.

**Table 1** *Open Caveats for the Cisco Unified IP Phone 7960G and 7940G (SIP) for Firmware Release 8.8*

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsk23270</a>	SIP call fails because Cisco Unified IP Phone 7940G adds port in ACK request Uniform Resource Identifier (URI)  <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk23270">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk23270</a>

## Resolved Caveats

[Table 2](#) lists Severity 1, 2, and 3 defects that are resolved for the Cisco Unified IP Phone 7960G and 7940G (SIP) using firmware release 8.8.

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that [Table 2](#) reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of resolved defects, access Bug Toolkit as described in the “[Using Bug Toolkit](#)” section on page 2.

**Table 2** *Resolved Caveats for the Cisco Unified IP Phone 7960G and 7940G (SIP) for Firmware Release 8.8*

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsi93026</a>	SIP phones generate multiple registration attempts and alarm errors  <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsi93026">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsi93026</a>
<a href="#">CSCsj02046</a>	Ringback is not heard by SIP caller  <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj02046">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj02046</a>

## Obtaining Documentation, Obtaining Support, and Security Guidelines

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly *What's New* in Cisco Product Documentation, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

## Cisco Product Security Overview

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: <http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>. If you require further assistance please contact us by sending email to [export@cisco.com](mailto:export@cisco.com).

---

CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0711R)

Any Internet Protocol (IP) addresses used in this document are not intended to be actual addresses. Any examples, command display output, and figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses in illustrative content is unintentional and coincidental.

© 2007 Cisco Systems, Inc. All rights reserved.