Release Notes for the Cisco WAP131 Wireless-N Dual Radio Access Point Firmware Version 1.0.2.13

May 2017

These release notes describe the known issues in the Cisco WAP131 Wireless-N Dual Radio Access Point firmware version 1.0.2.13.

Issues Resolved in 1.0.2.13 Release

- WAP131 may crash and reboot during upgrade. (CSCvc23612)

Known Issues

The following table lists the known issues in firmware version 1.0.2.13:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. **Workaround** None.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/ tsd_cisco_small_business _support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/ smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP131	www.cisco.com/go/100_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/en/US/docs/switches/lan/ csb_switching_general/rcsi/ Switch_ClassA_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty