

Release Notes for StarOS™ Software Version 21.12.2

First Published: Feb 28, 2019 Last Updated: Mar 05, 2019

Introduction

This Release Note identifies changes and issues related to this software release. This emergency release is based on release 21.12.1 These release notes are applicable to the ASR5500, VPC-SI and VPC-DI platforms.

Release Package Version Information

Table 1 - Release Package Version Information

Software Packages	Version
StarOS packages	21.12.2, build 71343

Descriptions for the various packages provided with this release are located in Release Package Descriptions.

Feature and Behavior Changes

The following features and/or behavior changes have been introduced in this emergency release.

Refer to the <u>Release Change Reference</u> for a complete list of feature and behavior changes associated with the software release on which this emergency release is based.

Related Documentation

For a complete list of documentation available for this release, go to http://www.cisco.com/c/en/us/support/wireless/asr-5000-series/products-installation-and-configuration-quides-list.html.

Installation and Upgrade Notes

This Release Note does not contain installation and upgrade instructions. Refer to the existing installation documentation for specific installation and upgrade considerations.

Firmware Updates

There are no firmware upgrades required for this release.


Installation and Upgrade Notes

Software Integrity Verification

To verify the integrity of the software image you have from Cisco, you can validate the SHA512 checksum information against the checksum identified by Cisco for the software.

Image checksum information is available through the following mechanisms:

 Cisco.com Software Download Details: To find the checksum, hover the mouse pointer over the software image you have downloaded.



At the bottom you find the SHA512 checksum, if you do not see the whole checksum you can expand it by pressing the "..." at the

• .cksums file: A file containing software image checksum information is distributed with the image files. The naming convention for this file is:

on>.cksums

Example: asr5500-21.4.0.cksums

To validate the information, calculate a SHA512 checksum using the information in $\underline{\text{Table 2}}$ and verify that it matches either the one provided on the software download page.

To calculate a SHA512 checksum on your local desktop please see the table below.

Table 2 - Checksum Calculations per Operating System

Operating System	SHA512 checksum calculation command examples	
Microsoft Windows	Open a command line window and type the following command	
	> certutil.exe -hashfile <filename>. <extension> SHA512</extension></filename>	
Apple MAC	Open a terminal window and type the following command	
	\$ shasum -a 512 <filename>.<extension></extension></filename>	

Open Bugs in this Release

Operating System	SHA512 checksum calculation command examples		
Linux	Open a terminal window and type the following command	Open a terminal window and type the following command	
	\$ sha512sum <filename>.<extension></extension></filename>		
	Or		
	<pre>\$ shasum -a 512 <filename>. <extension></extension></filename></pre>		

NOTES:

<filename> is the name of the file.

<extension> is the file extension (e.g. .zip or .tgz).

If the SHA512 checksum matches, you can be sure that no one has tampered with the software image or the image has not been corrupted during download.

If the SHA512 checksum does not match, we advise you to not attempt upgrading any systems with the corrupted software image. Download the software again and verify the SHA512 checksum again. If there is a constant mismatch, please open a case with the Cisco Technical Assistance Center.

Certificate Validation

In 21.12.0 and later releases, software images for StarOS, VPC-DI, and VPC-SI, and the companion software packages for StarOS and VPC are signed via x509 certificates. In pre-21.12.0 releases, image signing is not supported for VPC-DI and VPC-SI images, and for StarOS and VPC companion software packages.

USP ISO images are signed with a GPG key.

For more information and instructions on how to validate the certificates, refer to the README file available with the respective software packages.

Open Bugs in this Release

The following table lists the known bugs that were found in, and/or that remain open in this software release.

NOTE: This software release may contain open bugs first identified in other releases. Additional information for all open bugs for this release are available in the <u>Cisco Bug Search Tool</u>.

Table 3 - Open Bugs in this Release

Bug ID	Headline	Product Found*
CSCvm83524	[BP-CUPS] Assert failure at egtpc_handle_user_sap_event()	cups-cp
CSCvn63100	[BP-CUPS] Assert at saegwdrv_ue_fsm_st_active_evt_snx_line_callstate()	cups-cp
	[BP-CUPS] Observing new IE Interface: SXa wrongly sent in PFCP Heartbeat	
CSCvn80152	Request/Response	cups-cp
CSCvn44898	[PLT-CUPS-VPP] : TCP Flows are not getting cleared after FIN is received	cups-up
CSCvn75110	[BP-CUPS] High memory utilization by sessmgr - probable memory leak	cups-up

CSCV001375	und*
CSCvo07207 [BP-CUPS] sessctrl restart in UP cups-up [PLT-CUPS] [PLT-ICUPS] CUPS VPP task restart observed on UP and VPP task cups-up [BP-CUPS] UP gets stuck when disassociated and associated with new CP with different ECS config cups-up CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo755676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all [BP-ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads	
CSCvo25826 [PLT-ICUPS] CUPS VPP task restart observed on UP and VPP task not recovered too cups-up [BP-CUPS] UP gets stuck when disassociated and associated with new CP with different ECS config cups-up with different ECS cups-up with	
CSCvo25826 not recovered too cups-up [BP-CUPS] UP gets stuck when disassociated and associated with new CP with different ECS config CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mmee CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo155676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw CSCvo35584 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [BP-ICUPS]: sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo25826 not recovered too cups-up [BP-CUPS] UP gets stuck when disassociated and associated with new CP with different ECS config CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mmee CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo155676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw CSCvo35584 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [BP-ICUPS]: sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme CSCvo55100 Clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]: VI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32182 [BP-ICUPS]: Some UDP streams going to passive post ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw CSCvo35584 [BP-ICUPS]: Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo48775 EPC: MME, MEC - Inter-MME S1 HO trigger unexpected detach mme clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mme CSCvo55100 Subscribers stats mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo55676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]:X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw [BP-ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo55100 clear mme-service statistics not clearing Dual Connectivity with NR Subscribers stats mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15676 [BP-CUPS]:Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw CSCvo35584 [SP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw CSCvo75072 [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo55100 Subscribers stats mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvo155676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw CSCvo35584 [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw CSCvo75072 [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo15422 mmemgr task restart due to a segmentation in S1ap mme CSCvn55676 [BP-CUPS]: Uplink Stream remain in Config state after Flow status change pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all [BP-ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo27235 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all [BP-ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo31100 [BP-ICUPS]: vpp_main stuck in warn state pdn-gw CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo31100 [BP-ICUPS]X3 table entries absent post DMX migration pdn-gw CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo32182 [BP-ICUPS]: LI intercept failures on HSLI after ICSR switchover pdn-gw CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo32237 [BP-ICUPS]: some UDP streams going to passive post ICSR switchover pdn-gw [Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
[Smoke2] unexpected flows in sh active-charging flows all and sh active-charging subsystem all pdn-gw [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo35584 charging subsystem all [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo35584 charging subsystem all pdn-gw [BP:ICUPS]:Sessmgr restart@fapi_tp_process_incoming_local_row_req on DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvn75072 DPC2 card reboot. pdn-gw [BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
[BP-ICUPS]Unable to get over 4.3 Gbps on HSLI without fifo Q full on threads pdn-gw	
CSCvo30174 threads pdn-gw	
BP-ICUPS]:sessmgr 0 error fastpath_stream_add(): Stream [Ver: 0, locus: 2,	
,	
CSCvo32889 client_id: 8, stats_tabl sae-gw	
[PLT-ICUPS] Hundreds of Sessmgr asserts for	
CSCvo42844 fapi_tp_restart_notify_internal() on 21.12.0.71244 sae-gw	
[BP-ICUPS] Possible slowness in ECS CLI's on 21.12.71244 EFT versus earlier	
CSCvo48737 21.6 or 21.8 builds sae-gw	

Resolved Bugs in this Release

Bug ID	Headline	Product Found*
CSCvo49917	[BP-ICUPS] sessctrl in Over state on 21.12.0.71244 EFT	sae-gw
CSCvi12541	bfdlc facility instances in warn state on active and standby chassis	sae-gw
CSCvo31408	saegw-service stats not updating for CSRsp denied due to license exceeded	sae-gw
CSCvn94523	F2725: Rab Rel Response counters are not pegged	sgsn
CSCvo27835	[BP-ICUPS-saegw-DPC2]: HSLI - intercept failures observed due to tx fifo full	staros
CSCvo49923	[BP-ICUPS] Fastpath errors flooding syslog messages on 21.12.0.71244 EFT	staros
	[BP-ICUPS] Streams are not getting recovered after Planned DPC2	
CSCvn79019	Migration with 5g calls	staros
CSCvo04967	StarOS cannot assign multiple IPv6 address for diameter peer	staros
* Information in	the "Product Found" column identifies the product in which the bug was initially identified.	I.

Resolved Bugs in this Release

The following table lists the known bugs that are resolved in this specific software release.

NOTE: This software release may contain bug fixes first introduced in other releases. Additional information for all resolved bugs for this release are available in the <u>Cisco Bug Search Tool</u>.

Table 4 - Resolved Bugs in this Release

Bug ID	Headline	Product Found*
CSCvo39413	EPC: MME, M bit set in AIR-Flags in AIR message by MME	mme
[BP-ICUPS]: For a Pure-SGW call packet drops are seen in uplink and downlink direction. sgw		
* Information in the "Product Found" column identifies the product in which the bug was initially identified.		

Operator Notes


StarOS Version Numbering System

The output of the **show version** command displays detailed information about the version of StarOS currently running on the ASR 5x00 or Cisco Virtualized Packet Core platform.


Prior to release 16.1, the *Image Version* field displayed a branch of software including the build number, for example "16.0 (55435)". Subsequent releases of software for the major release differed only in build number. Lab Quality/EFT releases versus deployment releases also differed only in build number.

From release 16.1 onwards, the output of the **show version** command, as well as the terminology used to describe the Build Version Number fields, has changed. Additionally, **show version** will display slightly different information depending on whether or not a build is suitable for deployment.

The Version Build Number for releases between 16.1 and 21.0 include a major, maintenance, and emergency release number, for example "16.1.2".



The Version Build Number for releases 21.1 and later include a major and emergency release number, for example, "21.1.1".



In either scenario, the appropriate version number field increments after a version has been released. The new version numbering format is a contiguous sequential number that represents incremental changes between releases. This format will facilitate identifying the changes between releases when using Bug Search Tool to research software releases.

Release Package Descriptions

<u>Table 5</u> provides descriptions for the packages that are available with this release.

Table 5 - Release Package Information

In 21.12.0 and later Releases	In pre-21.12.0 Releases	Description
ASR 5500		

In 21.12.0 and later	In pre-21.12.0 Releases	Description
Releases asr5500- <release>.zip</release>	asr5500- <release>.bin</release>	Contains the signed ASR 5500 software image, the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
asr5500_T- <release>.zip</release>	asr5500_T- <release>.bin</release>	Contains the signed, trusted ASR 5500 software image, the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
StarOS Companion Pack	age	
companion- <release>.zip</release>	companion- <release>.tgz</release>	Contains numerous files pertaining to this version of the StarOS including SNMP MIBs, RADIUS dictionaries, ORBEM clients. These files pertain to both trusted and non-trusted build variants. In 21.12.0 and later releases, the StarOS companion package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate
VPC-DI		the certificate.
	l avena di malagga, bia	Contains the VDC Dibinary of the second that is used to use to
qvpc-di- <release>.bin.zip</release>	qvpc-di- <release>.bin</release>	Contains the VPC-DI binary software image that is used to replace a previously deployed image on the flash disk in existing installations.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di_T- <release>.bin.zip</release>	qvpc-di_T- <release>.bin</release>	Contains the trusted VPC-DI binary software image that is used to replace a previously deployed image on the flash disk in existing installations.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di- <release>.iso.zip</release>	qvpc-di- <release>.iso</release>	Contains the VPC-DI ISO used for new deployments, a new virtual machine is manually created and configured to boot from a CD image.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di_T- <release>.iso.zip</release>	qvpc-di_T- <release>.iso</release>	Contains the trusted VPC-DI ISO used for new deployments, a new virtual machine is manually created and configured to boot from a CD image.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di-template- vmware- <release>.zip</release>	qvpc-di-template- vmware- <release>.tgz</release>	Contains the VPC-DI binary software image that is used to on-board the software directly into VMware.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.

11.	T. B.I	In
In 21.12.0 and later Releases	In pre-21.12.0 Releases	Description
qvpc-di-template- vmware_T- <release>.zip</release>	qvpc-di-template- vmware_T- <release>.tgz</release>	Contains the trusted VPC-DI binary software image that is used to onboard the software directly into VMware.
release.	ricicuser rigz	In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di-template- libvirt-kvm-	qvpc-di-template- libvirt-kvm-	Contains the same VPC-DI ISO identified above and additional installation files for using it on KVM.
<release>.zip</release>	<release>.tgz</release>	In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di-template- libvirt-kvm_T-	qvpc-di-template- libvirt-kvm_T-	Contains the same trusted VPC-DI ISO identified above and additional installation files for using it on KVM.
<release>.zip</release>	<release>.tgz</release>	In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di- <release>.qcow2.zip</release>	qvpc-di- <release>.qcow2.tgz</release>	Contains the VPC-DI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-di_T- <release>.qcow2.zip</release>	qvpc-di_T- <release>.qcow2.tgz</release>	Contains the trusted VPC-DI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
VPC-SI		
qvpc-si- <release>.bin.zip</release>	qvpc-si- <release>.bin</release>	Contains the VPC-SI binary software image that is used to replace a previously deployed image on the flash disk in existing installations.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si_T- <release>.bin.zip</release>	qvpc-si_T- <release>.bin</release>	Contains the trusted VPC-SI binary software image that is used to replace a previously deployed image on the flash disk in existing installations.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.

In 21.12.0 and later	In pre-21.12.0 Releases	Description
Releases	III pre-21.12.0 Releases	Description
qvpc-si- <release>.iso.zip</release>	qvpc-si- <release>.iso</release>	Contains the VPC-SI ISO used for new deployments, a new virtual machine is manually created and configured to boot from a CD image.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si_T- <release>.iso.zip</release>	qvpc-si_T- <release>.iso</release>	Contains the trusted VPC-SI ISO used for new deployments a new virtual machine is manually created and configured to boot from a CD image.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si-template- vmware- <release>.zip</release>	qvpc-si-template- vmware- <release>.ova</release>	Contains the VPC-SI binary software image that is used to on-board the software directly into VMware.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si-template- vmware_T- <release>.zip</release>	qvpc-si-template- vmware_T- <release>.ova</release>	Contains the trusted VPC-SI binary software image that is used to onboard the software directly into VMware.
Neleasez.zip	Neleasez.ova	In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si-template-libvirt- kvm- <release>.zip</release>	qvpc-si-template-libvirt- kvm- <release>.tgz</release>	Contains the same VPC-SI ISO identified above and additional installation files for using it on KVM.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si-template-libvirt- kvm_T- <release>.zip</release>	qvpc-si-template-libvirt- kvm_T- <release>.tgz</release>	Contains the same trusted VPC-SI ISO identified above and additional installation files for using it on KVM.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si- <release>.qcow2.zip</release>	qvpc-si- <release>.qcow2.gz</release>	Contains the VPC-SI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.
qvpc-si_T- <release>.qcow2.zip</release>	qvpc-si_T- <release>.qcow2.gz</release>	Contains the trusted VPC-SI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.
		In 21.12.0 and later releases, this package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.

Obtaining Documentation and Submitting a Service Request

In 21.12.0 and later Releases	In pre-21.12.0 Releases	Description
VPC Companion Package		
companion-vpc- <release>.zip</release>	companion-vpc- <release>.tgz</release>	Contains numerous files pertaining to this version of the VPC including SNMP MIBs, RADIUS dictionaries, ORBEM clients. These files pertain to both VPC-DI and VPC-SI, and for trusted and non-trusted build variants. In 21.12.0 and later releases, the VPC companion package also includes the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation*, at: http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html.

Subscribe to What's New in Cisco Product Documentation, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

Obtaining Documentation and Submitting a Service Request

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2019 Cisco Systems, Inc. All rights reserved.