



END-OF-LIFE, NO. 1126

ADDENDUM TO ORIGINAL END-OF-SALE AND END-OF-LIFE NOTICE FOR CISCO 7200 SERIES NPE-175 NETWORK PROCESSING ENGINE

| | |
|-------------------------------|------------------------|
| Addendum date | November 5, 2004 |
| Effective date | September 1, 2004 |
| Original bulletin information | Product Bulletin #1126 |

The end-of-sale date for the Cisco® 7200 Series NPE-175 Network Processing Engine was July 15, 2000. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until July 15, 2005.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco NPE-175. Table 2 lists the product part numbers affected by this announcement and replacement product information. This notice is an addendum to the original Cisco NPE-175 end-of-sale and end-of-life bulletin.

The end of software support for the Cisco NPE-175 follows:

- Software support ends in Cisco IOS® Software releases 12.1(14)E, 12.2(24), 12.0(27)S, and 12.2(15)T.
- Bug fixes will be provided for 36 months after the Cisco NPE-175 end-of-sale date (July 15, 2000).
- The last date to receive support from the Cisco TAC is July 15, 2005.

Table 1. End-of-Life Milestones and Dates for Cisco NPE-175

| Milestone | Definition | Date |
|---|---|---|
| End-of-sale date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | July 15, 2000 |
| Last shipment date | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | October 15, 2000 |
| End of software maintenance releases date | The last date that Cisco Engineering may release any software maintenance releases or bug fixes to the software product. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. The last software releases supported include Cisco IOS Software releases 12.2(24), 12.2(15)T, 12.0(27)S, and 12.1(14)E. | 12.0(27)S: July 15, 2003 12.1(14)E: July 15, 2003 12.2(15)T: July 15, 2003 12.2(24): July 15, 2003 |
| End of service contract renewal | The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support. | July 15, 2004 |
| Last date of support | The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete. | July 15, 2005 |

Table 2. Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description |
|---------------------------------|---|---------------------------------|---|
| NPE-175 | NPE-175 Network Processing Engine for 7200 | NPE-400 | 7200VXR NPE-400 (128 MB default memory) |
| NPE-175= | NPE-175 Network Processing Engine for 7200, Spare | NPE-400= | 7200VXR NPE-400 (128 MB default memory), SPARE |
| CISCO7204VXR/175 | 7204VXR Bundle with NPE-175 and I/O Controller without FE | C7206VXR/400/2FE | 7206VXR with NPE-400 and I/O Controller with 2 FE/E Ports |

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco NPE-175 is the Cisco NPE-400. Note that the Cisco NPE-400 requires a Cisco 7200VXR chassis. More information about the Cisco NPE-400 can be found at:

http://www.cisco.com/en/US/prod/collateral/routers/ps341/product_data_sheet09186a00800ae715.html.

PRODUCT TMP OPTIONS

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco Systems® equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about the Cisco 7200 Series Router, go to <http://www.cisco.com/en/US/products/hw/routers/ps341/index.html> or contact your Cisco account manager or Cisco channel partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0406R) Pa/LW7351 11/04